

3559-75

12-97

3559_75

Steel strip for armouring cables.
Specifications

12 3100

01.01.77

(, . . 3, 4).

1.

1.1. :
— ;
— ,

1.2. :
— ,
; 1 — , , , ;

1.3. — 1;
— 2.

1.3 . (, . . 3).

1.4. :
—
—

PI— (300).
PH— (300).

(, . . 3).

1.5.

1.

©
©

, 1975
, 1998

CJ § 3								
			- 1	-				-Pl, -
0,10	-0,04		-0,02	-	10, 15, 20	-1,0	-0,4	-1,0
0,20	-0,07	-0,06	-0,04	-0,06	10, 15, 20, 25	-1,0	-0,4	-1,0
					30, 35	-2,0		-2,0
					40, 45	-3,0	-0,5	-3,0
					50, 55, 60	-4,0		-4,0
					10, 15, 20, 25	-1,0	-0,4	-1,0
0,30	-0,07	-0,06	-0,05	-0,06	30, 35	-2,0		-2,0
					40, 45	-3,0	0,5	-3,0
					50, 55, 60	-4,0		-4,0
					10, 15, 20, 25	-1,0	-0,4	-1,0
0,40	-0,11	-0,08	-0,06	-0,08	30, 35	-2,0		-2,0
					40, 45	-..		-3,0
					50, 55, 60	-4,0		-4,0
					10, 15, 20, 25	-1,0		-1,0
0,50	-0,11	-0,08	-0,07	-0,08	30, 35	-2,0	0,4	-2,0
					40, 45	-3,0		-3,0
					50, 55, 60	-4,0	-0,5	-4,0
					45	-3,0		-3,0
0,80	-0,16	-0,13	-0,09	-0,12	50, 55, 60	-4,0	-0,5	-4,0
					45	-3,0		-3,0
1,0	-0,20	-0,16	-0,10	0,14	50, 55, 60	-4,0	-0,5	-4,0
					45	-3,0		-3,0

0,5 1680 1700

+ 0,06

0,50 , 10

1-2-0,5 10 3559-75

1-2-0,5 10 3559-75.

50 : , 0,8 ,

- -0,8 50 3559-75.

(, . 3, 4).

260 ±2

0,30 321

±2

(, . 4).

0,08

2.

2.1.

1050, 380, 16523

(2.2. , . 3, 4).

(2.3. , . 2.5 2.6. 3).

30 %

(2.4. , . 2, 3).

2.5. 180° (E?=4),

2.4, 2.5. (2.6. 20 — 1 3).

2.6. , / 2, ;

200— 1- ;
100— 2- .

2.7. , . 2.

2

	(/ ²) , / ²	6 ₄ , %,
	280 (28)	20
!	280-400 (28-40)	23
		20

(2.8. , . 2).

175—205

300

2.9. 200 Anpl

150

300

2.10. ()

2,5

:

15— 10 ;
25— 15—55 ;
35— 60 .

Anpl,

(2.8—2.10. (, . 2, 3)).

3 2.11.

0,1-0,3 0,4-1,0	550-650 700—750

30 (400 1000 3, 4).

3.

3.1.

(3.2), ..., 1, 2).

2 % ()

2 % (),

().

3.4.

10 %

(),

3.5.

(, . . 3).

4.

4.1.

(6507).

3

(, . . . 3).

()

43

14019.

()

4.4.

(),

4

441

	,
10, 15, 20, 25	100
30, 35, 40, 45, 50, 55, 60	50

442

4.4.2. $\frac{b}{l} = 0,1 / 2$ $\frac{0,001}{l^2} = \frac{1}{l^2}$ $\frac{1}{l^2} = \frac{1}{b^2}$ $\frac{1}{l^2} = \frac{1}{(0,1)^2}$ $\frac{1}{l^2} = \frac{1}{0,01}$ $\frac{1}{l^2} = 100$ $l^2 = \frac{1}{100}$ $l = \frac{1}{10}$ $l = 0,1$

20
20
20
20
10 ;
* > 15 ;
* > 20 .

4.6.

(, . 3).

5. , , ,

5.1. () 3560, 3282

(), (),

(5.2. , . 1).

1:3,	203	38.01436	-12	-20	20799
1:3, -17	10877.				20799
				216	

(, . 3, 4).

5.3. 5.3.1. () () () 1
() () () 3560

(5.3.2. , . 3). () 5,0 ()

() 3560 10—15°.

(, . 1, 3).


9569;
8828;

(5.3. , . 1, 3).

(5.4. , . 3).

14192.

(, . 3).





6.

6.1.

6

. 6. (, . 3).





.(, . . 3).

1.

2.

17.12.75 3926

3.

3559-63

4.

,	,	,	,
166-89	4.1	9569-79	5.3.3
380-94	2.1	10877—76	5.2
1050-88	2.1	11701-84	4.5
3118-77	4.4.2	14019—80	4.3
3282-74	5.1	14192-96	5.4
3560-73	5.1, 5.3.1, 5.3.2	16523-89	2.1
4204-77	4.4.2	20799-88	5.2
6507-90	4.1	38.01436—87	5.2
8828-89	5.3.3		

5.

5—94

(11—12—94)

6.

1983 (1998 .) 1981 .,
1986 ., 1990 .(1, 2, 3, 4,
1—82, 5—83, 2—87, 8—90)

021007 10.08.95. 08.06.98. 24.07.98. . . 1,40. . . 0,94.
181 . 914. . 273. , 107076, , , 14.